

Concern over Hayagriva Madhav Temple repairs



Comments 0



Daya Nath Singh 18 November 2016 Updated 19 Nov 15665 views

Archaeological [Survey](#) of [India](#), Guwahati circle, has been trying to take-up the work of repairing of a broken pillar in the Mandap of Hayagriva [Madhav](#) Temple at [Hajo](#) for a long time. ASI, Guwahati has informed the media through a press note that one of the pillars of ancient [temple](#) was broken in three parts due to rusting of the iron dowels holding each other and the other developed cracks due to the same reason and widened more after the earthquake of May 2015. Hayagriva [Madhav Temple](#) is a reconstructed [temple](#) during the Koch period. The architectural parts of the earlier [temple](#) have been used for reconstruction. Different parts of the [temple](#) have been used randomly for making the pillars [over](#) which the arches are made with brick work in lime mortar [over](#) which the stone slab roof was laid, the press note added.

ASI, Guwahati circle has been trying to take up the work of repairing of the pillar in the Mandap of the [temple](#) since long. In this connection two expert committee meetings were held for the same in the year 2014 and 2015, but due to non-availability of stone masons, the work could not be taken up. In the first meeting it was decided to completely change the broken parts in 2014, but it would have been a major conservation work and the [temple](#) would have to be closed for 3-4 months. Since it would have been major conservation work, it was not acceptable to the [Temple](#) Committee.

The second committee was formed to look into the other alternative, proposed that the stone has not moved in the last 30-40 years, therefore the replacing of stone was not required. It recommended that the broken stone should be consolidated by bolting and filling up the voids with stone dust and epoxy-resin. But the work could not be taken up because the masons to come from Odisha did not turn up.

In March [2016](#), with the posting of new Assistant Superintending

Archeological Engineer and his expertise in taking such works in the past in Kolkata circle, helped Guwahati circle to take-up the said work. For this the firm which is taking up the work of conservation of Jagannath Temple at Puri was asked to come and give their suggestion for the same. Manas Kr Panda of firm New Pragati visited [Hajo](#) on August 19, [2016](#) and suggested that the bolting would cause vibration while drilling the stone which would be harmful for the structure. He suggested a few measures to the authorities and some steps have been taken up to prevent further cracks in the affected parts of the pillars, release added.

Daya Nath Singh

Journalist; Guwahati Press Club office Secretary

BY DAYA NATH SINGH

'Gamusa' politics come on fore during festivals only

Politics on Assam Accord

Politics is a 'chronic disease' that haunts a politician life long

Siddhartha Bhattacharjee felicitated

Assam steps up towards a clean administration

ON THIS DAY

Naina Subba Tunghahwngphe crowned Sikkim Miss Limbu 2024

০০০০ ০০ ০০০০০০ ০০০০ ০০০০ ০০০০০০

Tripura assembly passes 10 bills without debate

Gift to a father

New political party forms in BTAD

RELATED

A heartfelt tribute to poet Anis Uz Zaman

Tension grips Bihubar after youth social worker's killing

New Delhi BRICS Summit: Hoping for a Permanent Indian Presence in the UNSC

Israeli Journalist Gideon Levy Receives 2026 PEC Award

Rodali Bora Carries Assam's Sattriya and Bihu Heritage to the UK
